

**PHOTOGRAPHS**

**PHOTOGRAPH #1**



**BUILDING 2  
SECTION D**

Construction debris and trash scattered around the building. Contractor to cleanup.

**PHOTOGRAPH #2**



**BUILDING 2  
UNIT 216**

Contractor removed nail installed improperly at window header and refastened.

**PHOTOGRAPH #3**



**BUILDING 3  
SECTION A**

Contractor covered open walls with heavy duty poly sheeting to prevent water intrusion.

**PHOTOGRAPH #4**



**BUILDING 3  
SECTION A**

Contractor installed truss tie down straps per construction documents.

**PHOTOGRAPH #5**



**BUILDING 3  
SECTION B**

Contractor covered open walls with heavy duty poly sheeting to prevent water intrusion.

**PHOTOGRAPH #6**



**BUILDING 3  
SECTIONS C & D**

Contractor covered open walls with heavy duty poly sheeting to prevent water intrusion.

**PHOTOGRAPH #7**



**BUILDING 3  
SECTION E**

Contractor installed and painted soffit.

**PHOTOGRAPH #8**



**BUILDING 3  
SECTION F**

Contractor installed and painted soffit.

**PHOTOGRAPH #9**



**BUILDING 3  
SECTION F**

Contractor covered railing and building materials to prevent damage from rain.

**PHOTOGRAPH #10**



**BUILDING 3  
SECTION H**

Contractor installed and painted soffit.

**PHOTOGRAPH #11**



**BUILDING 3  
SECTION H**

Vent penetrations through Tyvek need flashing installed. Contractor to flash openings with DuPont FlexWrap.

**PHOTOGRAPH #12**



**BUILDING 6  
SECTION E**

Contractor covered open walls with heavy duty poly sheeting to prevent water intrusion.

**PHOTOGRAPH #13**



**BUILDING 6  
SECTION F**

Contractor covered open walls with heavy duty poly sheeting to prevent water intrusion.

**PHOTOGRAPH #14**



**BUILDING 3  
SECTION C**

Contractor covered open walls with heavy duty poly sheeting to prevent water intrusion.

**PHOTOGRAPH #15**



**BUILDING 6  
SECTION H**

Contractor covered open walls with heavy duty poly sheeting to prevent water intrusion.

**PHOTOGRAPH #16**



**BUILDING 6  
SECTION H**

Contractor made a strong effort to perform stud framing repairs between rainstorms.