

**PHOTOGRAPH #1**



**BUILDING 11  
SECTION B**

Contractor has erected access scaffolding and construction fencing designating work areas and overhead protection areas.

**PHOTOGRAPH #2**



**BUILDING 11  
SECTION C**

Contractor has erected access scaffolding and construction fencing designating work areas and overhead protection areas.

**PHOTOGRAPH #3**



**BUILDING 11  
SECTION D**

Contractor has erected access scaffolding and construction fencing designating work areas and overhead protection areas.

**PHOTOGRAPH #4**



**BUILDING 11  
SECTION E**

Contractor has removed stucco and sheathing board exposing wood framing for inspection and repairs.

**PHOTOGRAPH #5**



**BUILDING 11  
SECTION F**

Contractor has removed stucco and sheathing board exposing wood framing for inspection and repairs.

**PHOTOGRAPH #6**



**BUILDING 11  
SECTION G**

Contractor has removed stucco and sheathing board, then covered interior framed walls with heavy plastic for weather protection.

**PHOTOGRAPH #7**



**BUILDING 11  
SECTION H**

Contractor has removed existing stucco exposing the existing sheathing board.

**PHOTOGRAPH #8**



**BUILDING 11  
SECTION H**

Contractor has removed stucco and sheathing board, then and covered interior framed walls with heavy plastic for weather protection.

**PHOTOGRAPH #9**



**BUILDING 11  
STORAGE AREA**

Dumpster and equipment storage at North end of parking area.