

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 10
SECTION D**

Utility Box to be moved or removed.
Added to punch list.

PHOTOGRAPH #2



**BUILDING 10
SECTION D**

Dryer vent paint failing. Added to punch list.

PHOTOGRAPH #3



**BUILDING 10
SECTION F**

Construction materials on A/C equipment.
Added to punch list.

PHOTOGRAPH #4



**BUILDING 10
SECTION F**

Dryer vent paint failing. Added to punch list.

PHOTOGRAPH #5



**BUILDING 10
SECTION B**

Void in sealant at soffit transition. Added to punch list.

PHOTOGRAPH #6



**BUILDING 10
SECTION B**

Dryer vent paint failing. Added to punch list.

PHOTOGRAPH #7



**BUILDING 10
SECTION D**

Final clean up, removal of dumpster and construction materials. Added to punch list.