

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 21 SECTION F

Stucco sub-contractors applying finish coat of stucco.

PHOTOGRAPH #2



BUILDING 21 SECTION D

Stucco sub-contractors have completed three coat stucco system using Broco premixed stucco by Cemex.

PHOTOGRAPH #3



**BUILDING 21
SECTION D**

Stucco sub-contractors have completed three coat stucco system using Broco premixed stucco by Cemex.

PHOTOGRAPH #4



**BUILDING 21
SECTION C**

Balconies repairs and decking replacement completed. Simpson Strong -Tie hardware has not yet been installed.

PHOTOGRAPH #5



**BUILDING 21
SECTION B**

Stucco subcontractor has applied stucco accessories and metal lathing.

PHOTOGRAPH #6



**BUILDING 21
SECTION B- UNIT 2115**

Contractor finishing window interior sealant details, drywall replacement and drywall texture.

PHOTOGRAPH #7



**BUILDING 21
SECTION B- UNIT #2115**

Contractor finishing window interior sealant details, drywall replacement and drywall texture.

PHOTOGRAPH #8



**BUILDING 21
SECTION A**

Subcontractor has completed installation of JumboTex WRB and in process of applying stucco accessories and metal lathing.

PHOTOGRAPH #9



**BUILDING 20
SECTION H**

Contractor has performed framing repairs and gable end reinforcement repairs.

PHOTOGRAPH #10



**BUILDING 20
SECTION H**

BoraCare termite treatment applied at wall framing members by pest sub-contractor.

PHOTOGRAPH #11



**BUILDING 20
SECTION H**

Titan HD fasteners and Simpson Strong Tie connectors installed at base plate.

PHOTOGRAPH #12



**BUILDING 20
SECTION H**

Cross bracing gable reinforcement repairs in place.

PHOTOGRAPH #13



**BUILDING 20
SECTION H**

Simpson Strong-Tie strapping installed at cross bracing reinforcement.

PHOTOGRAPH #14



**BUILDING 20
SECTION A**

Contractor has performed balcony edge rail beam repair.

PHOTOGRAPH #15



**BUILDING 20
SECTION A**

Contractor replacing damaged breezeway framing.

PHOTOGRAPH #16



**BUILDING 20
SECTION A**

Pressure treated lumber delivered for built up beam repairs at balconies and breezeways.