

PHOTOGRAPHS


PHOTOGRAPH #1



BUILDING 20 SECTION A

New screen enclosures installed at lower patios.

PHOTOGRAPH #2



BUILDING 20 SECTION A

Florida Paints, Hi-performance aliphatic Urethane Enamel spray completed at railings.

PHOTOGRAPH #3



**BUILDING 20
SECTION C**

Florida Paints, Hi-performance aliphatic Urethane Enamel spray completed at railings.

PHOTOGRAPH #4



**BUILDING 20
SECTION D**

Stucco scratch coat and brown coat applications in progress.

PHOTOGRAPH #5



**BUILDING 20
SECTION E**

Three coat 7/8" stucco system installed.

PHOTOGRAPH #6



**BUILDING 20
SECTION F**

Stucco Brown coats and finish coats in progress.

PHOTOGRAPH #7



**BUILDING 20
SECTION F**

Stucco Brown coats and finish coats in progress.

PHOTOGRAPH #8



**BUILDING 20
SECTION F**

Stucco sub-contractor mixing Broco Stucco Cement with sand on site for stucco mix.

PHOTOGRAPH #9



**BUILDING 21
SECTION B**

Brackets attached from new screen enclosure to stucco installed completing the punch list items.

PHOTOGRAPH #10



**BUILDING 21
SECTION F**

Brackets attached from new screen enclosure to stucco installed completing the punch list items.