

## PHOTOGRAPHS

**PHOTOGRAPH #1**



### **BUILDING 7 SECTION H**

Contractor has begun demolition by removal of stucco.

**PHOTOGRAPH #2**



### **BUILDING 7 SECTION H**

Stucco and preexisting sheathing removal in progress.

**PHOTOGRAPH #3**



**BUILDING 7  
SECTION H**

Contractor's warning tag (requiring inspection and competent persons approval before scaffolding is use) is still in place.

**PHOTOGRAPH #4**



**BUILDING 7  
SECTION G**

Construction perimeter plastic fencing in place designating hard hat areas.

**PHOTOGRAPH #5**



**BUILDING 7  
SECTION G**

Contractor has begun demolition by removal of stucco and preexisting sheathing.

**PHOTOGRAPH #6**



**BUILDING 7  
SECTION F**

Balcony railings removed and placed on the ground.