

PHOTOGRAPH #1



**BUILDING 18
SECTION A**

Stucco sub-contractor installing vinyl stucco accessories as per drawings and specifications.

PHOTOGRAPH #2



**BUILDING 18
SECTION A**

Stucco sub-contractor protecting new windows with plastic covering prior to stucco applications.

PHOTOGRAPH #3



**BUILDING 18
SECTION A**

Stucco sub-contractor has applied scratch coat of stucco system as per ASTM C 926.

PHOTOGRAPH #4



**BUILDING 18
SECTION B**

Stucco sub-contractor protecting new windows with plastic covering prior to stucco applications.

PHOTOGRAPH #5



**BUILDING 18
SECTION B**

Stucco sub-contractor has applied brown coat of stucco system as per ASTM C 926.

PHOTOGRAPH #6



**BUILDING 18
SECTION B**

Stucco sub-contractor has applying finish coat of stucco system as per ASTM C 926.

PHOTOGRAPH #7



**BUILDING 18
SECTION C**

Stucco sub-contractor has applied full three coat 7/8" stucco system as per ASTM C 926.

PHOTOGRAPH #8



**BUILDING 18
SECTION C**

Contractor has begun priming new stucco.